

ASSEMBLY INSTRUCTION

CDH90 - 6' POSTER BED






HARDWARE LIST


NO	HARDWARE NAME	IMAGE	QTY (PCS)
①	METAL THREAD M8x70		20 PCS
②	HALF MOON WASHER		20 PCS
③	NUT M8		20 PCS
④	SPANNER M13		1 PC
⑤	FLAT WASHER M8		10 PCS
⑥	SPRING WASHER M8		10 PCS
⑦	BOLT M8x60		10 PCS
⑧	ALLEN KEY M4		1 PC
⑨	BOLT M6x50		2 PCS
⑩	SCREW 4*50		2 PCS
⑪	SCREW 4*30		10 PCS

PART LIST

A BACK LEG (L) = 1 PC 	B BACK LEG (R) = 1 PC 	C FRONT LEG (L) = 1 PC 	D FRONT LEG (R) = 1 PC 	E CROSS BAR (TOP) = 2 PCS 	F CROSS BAR (SIDE) = 2 PCS 	G FRAME FOOTBOARD = 1 PC
H CROSS BAR (BOTTOM) = 1 PC 	I FRAME HEADBOARD = 1 PC 	E CENTRE SUPPORT RAIL = 1 PC 	F CENTRE LEGS = 2 PCS 	C SIDE RAILS = 2 PCS 	D SLAT = 1PC 	

STEP 1







ASSEMBLY INSTRUCTION

CDH90 - 6' POSTER BED


STEP 2




STEP 3




STEP 4



STEP 5







ASSEMBLY INSTRUCTION

CDH90 - 6' POSTER BED

STEP 6



STEP 7



STEP 8

