

ASSEMBLY INSTRUCTION


UTD25 - DRESSING TABLE AND MIRROR

HARDWARE LIST


NO	HARDWARE NAME	IMAGE	QTY (PCS)
①	BOLT M6x35		4 PCS
②	BOLT M6x45		4 PCS
③	SPRING WASHER M6		8 PCS
④	FLAT WASHER M6		8 PCS
⑤	ALLEN KEY M4		1 PC

PART LIST

A TABLE = 1 PC




B MIRROR = 1 PC





C LEFT SUPPORT BAR = 1 PC



D RIGHT SUPPORT BAR = 1 PC



STEP 1



ASSEMBLY INSTRUCTION

UTD25 - DRESSING TABLE AND MIRROR

STEP 2

